

## *K100-40 Automatic Carton Opening Machine*



This machine is only applied to adhesive tape, cardboard boxes with or without tape, without function of carton alarm warning.

### **Main features:**

- 1) Can be place a minimum of 100 unformed cartons, add cartons any time.
- 2) Machine designing according to technological process of production line, requirements of plane layout, beautiful appearance, good manufacturing process, Operation, adjustment and maintenance easy and quick. Have safety protection function, such as over current protection, safe exit, etc.
- 3) Flow chart & maximum bug indication have a protection function
- 4) According to the quantity of the boxes on the convey belt, automatically adjusts the operating speed

### **Technical parameters:**

- Power: 380V, 50Hz, 25Kw
- Pressure: 4-6bar
- Tape Width: 4.8-6 .0 cm
- Speed: 52P/min
- Tape Length: 2000m
- Carton size: (250-350) × (180-250) × (220-300) can be customized
- Table Height: 1000-2000mm (adjustable)
- Dimensions: 3800 × 1530 × 2200 (mm)
- Weight: 1200kg