

FFA-MA Conveyor Feeding Packing Machine



FFA-MA adopt full servo motor control to achieve conveyor feeding. This machine do not need pusher, the photo cell will inspect the product length and adjust the sealer automatically achieve full automatic packing. So the machine can pack different sizes of product do not need to change anything.

Technical Parameters:

Packing speed		30-120
PackingRange	L(mm)	90-450
	W(mm)	10-200
	H(mm)	15-110
Electric Power Voltage(v)		220
Power consumption (kw)		4
Weight(kg)		1100
Dimensions (L*W*H)(mm)		Main machine: 4500*1250*1700
Packing Material		compound Film: Paper/PE, OPP/PE, OPP/AL/PE etc